

# 7CH - MATERIAL DE INSTALACIÓN CHINT



**7CHD4WS18132**  
BASE PORTAFUSIBLE 1P 32A  
WS18-1-32 CHINT

**7CHD1DIF22530**  
DIF. 2/25/30 NL1-2-25-30AC  
CHINT

**7CHD1DIF440300**  
DIF. 4/40/300 NL1-4-40-300AC  
CHINT

**7CHD1NS22525**  
GUARDAMOTOR 3P NS2-25-25  
CHINT

**7CHD1F11**  
CONT.AUXIL.INC+INO F11  
CHINT

**7CHD1DIF225300**  
DIF. 2/25/300 NL1-2-25-300AC  
CHINT

**7CHD1DIF46330**  
DIF. 4/63/30 NL1-4-63-30AC  
CHINT

**7CHD1NS22504**  
GUARDAMOTOR 3P NS2-25-4  
CHINT

**7CHD1NS2AU1125**  
CONT.AUXIL.INC+INO  
NS2AU11/25 CHINT

**7CHD1DIF24030**  
DIF. 2/40/30 NL1-2-40-30AC  
CHINT

**7CHD1DIF463300**  
DIF. 4/63/300 NL1-4-63-300AC  
CHINT

**7CHD1NS225063**  
GUARDAMOTOR 3P NS2-25-6.3  
CHINT

**7CHD1NC1309**  
CONTACTOR 3P NC1-3-09-10-  
220 CHINT

**7CHD1DIF240300**  
DIF. 2/40/300 NL1-2-40-300AC  
CHINT

**7CHD1NS225016**  
GUARDAMOTOR 3P NS2-25-1.6  
CHINT

**7CHD1NS280B40**  
GUARDAMOTOR 3P NS2-80B-  
40 CHINT

**7CHD1NC1312**  
CONTACTOR 3P NC1-3-12-10-  
220 CHINT

**7CHD1DIF26330**  
DIF. 2/63/30 NL1-2-63-30AC  
CHINT

**7CHD1NS22510**  
GUARDAMOTOR 3P NS2-25-10  
CHINT

**7CHD1NS280B63**  
GUARDAMOTOR 3P NS2-80B-  
63 CHINT

**7CHD1NC1318**  
CONTACTOR 3P NC1-3-18-10-  
220 CHINT

**7CHD1DIF263300**  
DIF. 2/63/300 NL1-2-63-300AC  
CHINT

**7CHD1NS22514**  
GUARDAMOTOR 3P NS2-25-14  
CHINT

**7CHD1MAG1P10**  
MAGNETO 1P 10A DZ47-1-10C  
CHINT

**7CHD1NC1325**  
CONTACTOR 3P NC1-3-25-10-  
220 CHINT

**7CHD1DIF42530**  
DIF. 4/25/30 NL1-4-25-30AC  
CHINT

**7CHD1NS22518**  
GUARDAMOTOR 3P NS2-25-18  
CHINT

**7CHD1MAG1P16**  
MAGNETO 1P 16A DZ47-1-16C  
CHINT

**7CHD1NC1332**  
CONTACTOR 3P NC1-3-32-10-  
220 CHINT

**7CHD1DIF425300**  
DIF. 4/25/300 NL1-4-25-300AC  
CHINT

**7CHD1NS225025**  
GUARDAMOTOR 3P NS2-25-2.5  
CHINT

**7CHD1MAG1P20**  
MAGNETO 1P 20A DZ47-1-20C  
CHINT

**7CHD1NC1340**  
CONTACTOR 3P NC1-3-40-11-  
220 CHINT

**7CHD1DIF44030**  
DIF. 4/40/30 NL1-4-40-30AC  
CHINT

**7CHD1NS22523**  
GUARDAMOTOR 3P NS2-25-23  
CHINT

**7CHD1MAG1P25**  
MAGNETO 1P 25A DZ47-1-25C  
CHINT

# 7CH - MATERIAL DE INSTALACIÓN CHINT

## 7CHD1MAG1P32

MAGNETO 1P 32C DZ47-1-32C  
CHINT

## 7CHD1MAG2P25

MAGNETO 2P 25A DZ47-2-25C  
CHINT

## 7CHD1MAG3P50

MAGNETO 3P 50A NB1-3-50C  
CHINT

## 7CHD1MAG4P63

MAGNETO 4P 63A NB1-4-63C  
CHINT

## 7CHD1MAG1PN10

MAGNETO 1P+N 1MOD 10A  
DZ267-1N-10C CHINT

## 7CHD1MAG2P32

MAGNETO 2P 32A DZ47-2-32C  
CHINT

## 7CHD1MAG3P63

MAGNETO 3P 63A NB1-3-63C  
CHINT

## 7CHD1NC636

MINICONTRACTOR NC6-3-6-10-  
220 CHINT

## 7CHD1MAG1PN16

MAGNETO 1P+N 1MOD 16A  
DZ267-1N-16C CHINT

## 7CHD1MAG2P40

MAGNETO 2P 40A DZ47-2-40C  
CHINT

## 7CHD1MAG4P10

MAGNETO 4P 10A NB1-4-10C  
CHINT

## 7CHD1NC639

MINICONTRACTOR NC6-3-9-10-  
220 CHINT

## 7CHD1MAG1PN20

MAGNETO 1P+N 1MOD 20A  
DZ267-1N-20C CHINT

## 7CHD1MAG3P10

MAGNETO 3P 10A NB1-3-10C  
CHINT

## 7CHD1MAG4P16

MAGNETO 4P 16A NB1-4-16C  
CHINT

## 7CHD4BB101

PUENTE MAGN. 1P BB101  
CHINT

## 7CHD1MAG1PN25

MAGNETO 1P+N 1MOD 25A  
DZ267-1N-25C CHINT

## 7CHD1MAG3P16

MAGNETO 3P 16A NB1-3-16C  
CHINT

## 7CHD1MAG4P20

MAGNETO 4P 20A NN1-4-20C  
CHINT

## 7CHD4BB201

PUENTE MAGN. 2P BB201  
CHINT

## 7CHD1MAG1PN32

MAGNETO 1P+N 1MOD 32A  
DZ267-1N-32C CHINT

## 7CHD1MAG3P20

MAGNETO 3P 20A NB1-3-20C  
CHINT

## 7CHD1MAG4P25

MAGNETO 4P 25A NB1-4-25C  
CHINT

## 7CHD4BB301

PUENTE MAGN. 3P BB301  
CHINT

## 7CHD1MAG2P10

MAGNETO 2P 10A DZ47-2-10C  
CHINT

## 7CHD1MAG3P25

MAGNETO 3P 25A NB1-3-25C  
CHINT

## 7CHD1MAG4P32

MAGNETO 4P 32A NB1-4-32C  
CHINT

## 7CHD4BB401

PUENTE MAGN. 4P BB401  
CHINT

## 7CHD1MAG2P16

MAGNETO 2P 16A DZ47-2-16C  
CHINT

## 7CHD1MAG3P32

MAGNETO 3P 32A NB1-3-32C  
CHINT

## 7CHD1MAG4P40

MAGNETO 4P 40A NB1-4-40C  
CHINT

## 7CHD4RHC230

RELOJ HORARIO RHC/230  
C/RESERVA

## 7CHD1MAG2P20

MAGNETO 2P 20A DZ47-2-20C  
CHINT

## 7CHD1MAG3P40

MAGNETO 3P 40A NB1-3-40C  
CHINT

## 7CHD1MAG4P50

MAGNETO 4P 50A NB1-4-50C  
CHINT